

# How to calibration

1



1. Turn on PH meter

2

6.86 pH Buffer Powder



2. Dissolve each buffer solution in 250ML of distilled water

3



3. Immerse the electrode into the PH 6.86 solution, (under the temperature of 25)

4



4. Press the "CAL" (calibration) button for 5 seconds and release  
-Display will start flashing 6.86